

# AMS02-PDS

DOC N°: PDS-RP-CGS-005

ISSUE: 1

DATE: 09/05/2008

PAGE: 1 of 3

### INSPECTION REPORT

APPLICABLE DOC. REF.

PROC. REF.

AMS02-PDS PFM Manufacturing and Inspection Plan PDS-PL-CGS-001

NA

ITEM INSPECTED (Name, P/N, S/N) AMS02-PDS PFM - BOARDS - Inspection Point.

### REQUIREMENT SATISFIED

Manufacturing according to aerospace standards

INSPECTION (Action/Results)

#### DESCRIPTION

Inspection was performed at Carlo Gavazzi Space premises starting on 9 May 2008 and was carried out on the following boards, detail of the inspected boards were below reported:

- 1) AUX DC/DC BOARD ASSY p/n:11-AMS02PDS-740.00 s/n:07/016/A.
- 2) AUX DC/DC BOARD ASSY p/n:11-AMS02PDS-740.00 s/n:07/015/D.
- 3) AUX DC/DC BOARD ASSY p/n:11-AMS02PDS-740.00 s/n:07/016/C.

### HARDWARE REVIEW

1) AUX DC/DC BOARD ASSY p/n:11-AMS02PDS-740.00 s/n:07/016/A, Assy:11-AMS02PDS-740.00 rev./, Parts List:11-AMS02PDS-740.01 rev./, Electrical Scheme:11-AMS02PDS-740.03 rev./, Master PCB:SPO-PD-020010-DR-03-CGS rev./.

The following NCRs were presented during the inspection:

- NCR-PDS-CGS-C-039(electrical connection missing), NCR classified "minor" is still open during the inspection activity, the following corrective actions will be performed: glue the added wire with adhesive EC 2216 B/A, perform a visual inspection of the previous rework.
- NCR-PDS-CGS-C-044(OVC protection improvement), NCR classified "minor" is still open during the inspection activity, the following corrective actions will be performed: glue the added components and wires with adhesive EC 2216 B/A, perform a visual inspection of the previous reworks.

The following PLVSs (Parts List Variation Sheet) were presented during the inspection:

- 11-AMS02PDS-740.01 rev / A1 can be considered closed.
- 11-AMS02PDS-740.01 rev / A2 can be considered closed.
- 11-AMS02PDS-740.01 rev / A3 can be considered closed.
- 11-AMS02PDS-740.01 rev / A4 can be considered closed.
- 11-AMS02PDS-740.01 rev / A12 can be considered closed.
- 11-AMS02PDS-740.01 rev / A14 can be considered closed.

The H/W has been visually inspected and is ok:no damage, visible clean is ok.

	Operator	Quality Assurance	C.C.
Signature		G. FRANCINE	C.CINQUEPALMI
Date		08/05/08 / 2	enger.



## AMS02-PDS

DOC N°: PDS-RP-CGS-005

ISSUE: 1

DATE: 09/05/2008

PAGE: 2 of 3

### INSPECTION REPORT

APPLICABLE DOC. REF.
See page 1

ITEM INSPECTED (Name, P/N, S/N)
See page 1

REQUIREMENT SATISFIED

See page 1

INSPECTION (Action/Results)

2) AUX DC/DC BOARD ASSY p/n:11-AMS02PDS-740.00 s/n:07/015/D, Assy:11-AMS02PDS-740.00 rev./, Parts List:11-AMS02PDS-740.01 rev./, Electrical Scheme:11-AMS02PDS-740.03 rev./, Master PCB:SPO-PD-020010-DR-03-CGS rev./.

The following NCRs were presented during the inspection:

- NCR-PDS-CGS-C-039(electrical connection missing), NCR classified "minor" is still open during the
  inspection activity, the following corrective actions will be performed: glue the added wire with adhesive
  EC 2216 B/A, perform a visual inspection of the previous rework.
- NCR-PDS-CGS-C-044(OVC protection improvement), NCR classified "minor" is still open during the
  inspection activity, the following corrective actions will be performed: glue the added components and
  wires with adhesive EC 2216 B/A, perform a visual inspection of the previous reworks.

The following PLVSs (Parts List Variation Sheet) were presented during the inspection:

- 11-AMS02PDS-740.01 rev / A1 can be considered closed.
- 11-AMS02PDS-740.01 rev / A2 can be considered closed.
- 11-AMS02PDS-740.01 rev / A3 can be considered closed.
- 11-AMS02PDS-740.01 rev / A4 can be considered closed.
- 11-AMS02PDS-740.01 rev / A12 can be considered closed.
- 11-AMS02PDS-740.01 rev / A14 can be considered closed.

The H/W has been visually inspected and is ok:no damage, visible clean is ok.

	Operator	Quality Assurance	C.C.
Signature		E. FRANCING	C.CINQUEPACHI
Date	2	08/05/08 /	3/5/8



## AMS02-PDS

DOC N°: PDS-RP-CGS-005

ISSUE: 1

DATE: 09/05/2008

PAGE: 3 of 3

#### INSPECTION REPORT

APPLICABLE DOC. REF.
See page 1

ITEM INSPECTED (Name, P/N, S/N)
See page 1

REQUIREMENT SATISFIED
See page 1

INSPECTION (Action/Results)

3) AUX DC/DC BOARD ASSY p/n:11-AMS02PDS-740.00 s/n:07/016/C, Assy:11-AMS02PDS-740.00 rev./, Parts List:11-AMS02PDS-740.01 rev./, Electrical Scheme:11-AMS02PDS-740.03 rev./, Master PCB:SPO-PD-020010-DR-03-CGS rev./.

The following NCRs were presented during the inspection:

- NCR-PDS-CGS-C-039(electrical connection missing), NCR classified "minor" is still open during the
  inspection activity, the following corrective actions will be performed: glue the added wire with adhesive
  EC 2216 B/A, perform a visual inspection of the previous rework.
- NCR-PDS-CGS-C-044(OVC protection improvement), NCR classified "minor" is still open during the
  inspection activity, the following corrective actions will be performed: glue the added components and
  wires with adhesive EC 2216 B/A, perform a visual inspection of the previous reworks.

The following PLVSs (Parts List Variation Sheet) were presented during the inspection:

- 11-AMS02PDS-740.01 rev / A1 can be considered closed.
- 11-AMS02PDS-740.01 rev / A2 can be considered closed.
- 11-AMS02PDS-740.01 rev / A3 can be considered closed.
- 11-AMS02PDS-740.01 rev / A4 can be considered closed.
- 11-AMS02PDS-740.01 rev / A12 can be considered closed.
- 11-AMS02PDS-740.01 rev / A14 can be considered closed.

The H/W has been visually inspected and is ok:no damage, visible clean is ok.

### CONCLUSION

All solder joints are of adequate quality, the soldering process complies to ECSS-Q-70-08 and ECSS-Q-70-38, all modifications are performed according to ECSS-Q-70-28.

The open points are here listed:

- NCR-PDS-CGS-C-039(electrical connection missing), NCR classified "minor" is still open during the
  inspection activity, the following corrective actions will be performed: glue the added wire with adhesive EC
  2216 B/A, perform a visual inspection of the previous rework.
- NCR-PDS-CGS-C-044(OVC protection improvement), NCR classified "minor" is still open during the inspection activity, the following corrective actions will be performed: glue the added components and wires with adhesive EC 2216 B/A, perform a visual inspection of the previous reworks.

Operator Quality Assurance C.C.

Signature E. FRANCINIO C.CINR EPACHI

Operator Quality Assurance C.C.

Signature 69/5/08 FT C.CINR EPACHI

Operator Quality Assurance C.C.

315(8)